

**Americans with Disabilities Act (ADA)
ADA Transition Plan for the Public Right-of-Way**



Appendix B2

GIS Sidewalk and Driveway ADA Inventory and Prioritization

May 2024

Prepared by Transportation Solutions, Inc.



Sidewalk Asset Inventory Data Fields and Attributes Collected in 2023

No	Field	Attribute
1	Grade	A (Fair/Better)
		B (Poor)
		C (Very Poor)
		D (Missing)
2	Condition	Fair or Better
		Poor
		Very Poor
		Missing (Needed but does not Exist)
3	Sidewalk Width	60" or greater
		48" to > 60" (PROWAG)
		36" to > 48" (ADAAG)
		Less than 36"
		Other
4	Cross Slope	Up to or equal to 2%
		More than 2%
5	Running Slope	Matches roadway grade
		Does not match roadway grade
6	Obstacle	Vegetation
		Utility Pole/Box
		Sign/Movable Object
		Fixed Object
		Upheaval
		PAR Overhead
		Other
7	Passing Zone Dimensions	Varies
8	Sidewalk Width Change Point	Location where width of sidewalk changes
9	SDI	Sidewalk Driveway Interface location
10	Notes	As needed
11	Attachments	Photo attached as .jpg
12	ADA Compliant	Yes
		No

2023 Skamania County
Sidewalk Segment GIS ADA Data

Sw_Seg_ID	SWSegADACompliance	Grade	Condition
1	No	C	Very Poor
2	No	C	Very Poor
3	No	C	Very Poor
4	Yes	A	Fair or Better
5		C	Other
6	No	B	Poor
7	No	C	Very Poor
8	No	B	Poor
9	No	B	Poor
10	No	B	Poor
11	No	B	Poor
12	No	B	Poor
13	No	B	Poor
14	No	B	Poor
15	No	B	Poor
16	No	B	Poor
17	No	B	Poor
18	No	B	Poor
19	No	B	Poor
20	No	B	Poor
21	No	A	Fair or Better
22	No	C	Very Poor
23	No	B	Poor
24	No	B	Poor
25	No	B	Poor
26	No	B	Poor
27	No	B	Poor
28	No	B	Poor
29	No	B	Poor
30	No	B	Poor
31	No	B	Poor
32	No	B	Poor
33	No	B	Poor
34	No	B	Poor
35	No	C	Very Poor
36	No	B	Poor
37	No	B	Poor
38	No	B	Poor
39	No	C	Very Poor
40	No	B	Poor
41	No	C	Very Poor
42	No	B	Poor
43	No	C	Very Poor
44	No	A	Fair or Better
45	No	C	Very Poor
46	Yes	A	Fair or Better
47	Yes	A	Fair or Better
48	No	C	Very Poor

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Grade	Condition	SDI	Width	Cross_Slope
2023001	No	B	Poor	<Null>	60" or more	More than 2%
2023002	No	C	Very Poor	<Null>	60" or more	More than 2%
2023003	No	C	Very Poor	Sidewalk Driveway Interface	60" or more	More than 2%
2023004	No	C	Very Poor	<Null>	60" or more	Up to or equal to 2%
2023005	No	C	Very Poor	<Null>	60" or more	More than 2%
2023006	Yes	A	Fair or Better	<Null>	60" or more	Up to or equal to 2%
2023007	Yes	A	Fair or Better	<Null>	60" or more	Up to or equal to 2%
2023010	No	B	Poor	<Null>	60" or more	Up to or equal to 2%
2023011	No	B	Poor	<Null>	60" or more	Up to or equal to 2%
2023012	No	C	Very Poor	<Null>	60" or more	More than 2%
2023013	No	B	Poor	<Null>	60" or more	More than 2%
2023014	No	C	Very Poor	<Null>	60" or more	Up to or equal to 2%
2023015	No	B	Poor	Sidewalk Driveway Interface	60" or more	More than 2%
2023016	No	B	Poor	Sidewalk Driveway Interface	60" or more	More than 2%
2023017	No	B	Poor	<Null>	60" or more	Up to or equal to 2%
2023018	No	B	Poor	<Null>	60" or more	More than 2%
2023019	No	B	Poor	<Null>	60" or more	More than 2%
2023020	No	B	Poor	<Null>	60" or more	Up to or equal to 2%
2023021	No	B	Poor	Sidewalk Driveway Interface	<Null>	Up to or equal to 2%
2023022	No	C	Very Poor	<Null>	60" or more	More than 2%
2023023	No	C	Very Poor	<Null>	60" or more	Up to or equal to 2%

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Grade	Condition	SDI	Width	Cross_Slope
2023024	No	B	Poor	<Null>	60" or more	More than 2%
2023025	No	B	Poor	<Null>	60" or more	Up to or equal to 2%
2023026	No	B	Poor	<Null>	60" or more	Up to or equal to 2%
2023027	No	B	Poor	<Null>	60" or more	More than 2%
2023028	No	B	Poor	<Null>	60" or more	Up to or equal to 2%
2023029	No	B	Poor	<Null>	60" or more	Up to or equal to 2%
2023030	No	B	Fair or Better	<Null>	60" or more	More than 2%
2023031	No	B	Poor	<Null>	60" or more	Up to or equal to 2%
2023032	No	B	Poor	<Null>	60" or more	Up to or equal to 2%
2023033	No	B	Poor	<Null>	60" or more	More than 2%
2023034	No	B	Poor	<Null>	60" or more	More than 2%
2023035	No	B	Poor	<Null>	60" or more	More than 2%
2023036	No	B	Poor	<Null>	60" or more	More than 2%
2023037	No	C	Very Poor	<Null>	60" or more	More than 2%
2023038	No	B	Poor	<Null>	60" or more	<Null>
2023039	No	C	Very Poor	<Null>	60" or more	<Null>
2023040	No	B	Poor	<Null>	60" or more	Up to or equal to 2%
2023041	No	C	Very Poor	<Null>	60" or more	<Null>
2023042	No	B	Poor	<Null>	60" or more	More than 2%
2023043	No	B	Poor	<Null>	60" or more	<Null>
2023044	No	C	Very Poor	<Null>	36" to >48"	More than 2%
2023045	No	C	Very Poor	Sidewalk Driveway Interface	48" to >60"	More than 2%
2023046	No	B	Poor	<Null>	48" to >60"	More than 2%

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Grade	Condition	SDI	Width	Cross_Slope
2023047	No	C	Very Poor	Sidewalk Driveway Interface	48" to >60"	More than 2%
2023048	No	C	Very Poor	Sidewalk Driveway Interface	<Null>	More than 2%
2023049	No	C	Very Poor	<Null>	36" to >48"	More than 2%
2023050	No	B	Poor	<Null>	48" to >60"	More than 2%
2023051	No	B	Poor	<Null>	36" to >48"	More than 2%
2023052	No	B	Poor	Sidewalk Driveway Interface	36" to >48"	More than 2%
2023053	No	B	Poor	<Null>	48" to >60"	More than 2%
2023054	No	B	Poor	<Null>	48" to >60"	More than 2%
2023055	No	C	Very Poor	<Null>	48" to >60"	More than 2%
2023056	No	C	Very Poor	<Null>	48" to >60"	More than 2%
2023057	No	B	Poor	<Null>	<Null>	More than 2%
2023058	No	B	Poor	<Null>	36" to >48"	More than 2%
2023059	No	B	Poor	Sidewalk Driveway Interface	48" to >60"	More than 2%
2023060	No	B	Poor	Sidewalk Driveway Interface	48" to >60"	More than 2%
2023061	No	B	Poor	Sidewalk Driveway Interface	48" to >60"	More than 2%
2023062	No	B	Poor	<Null>	36" to >48"	More than 2%

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Grade	Condition	SDI	Width	Cross_Slope
2023063	No	B	Poor	<Null>	36" to >48"	More than 2%
2023064	No	B	Poor	<Null>	36" to >48"	More than 2%
2023065	No	B	Poor	<Null>	48" to >60"	Up to or equal to 2%
2023066	No	B	Poor	<Null>	48" to >60"	Up to or equal to 2%
2023067	No	B	Fair or Better	<Null>	48" to >60"	<Null>
2023068	No	B	Poor	<Null>	48" to >60"	Up to or equal to 2%
2023069	No	B	Poor	<Null>	36" to >48"	Up to or equal to 2%
2023070	No	B	Poor	Sidewalk Driveway Interface	48" to >60"	More than 2%
2023071	No	B	Poor	<Null>	36" to >48"	More than 2%
2023072	No	B	Poor	<Null>	48" to >60"	More than 2%
2023073	No	B	Poor	<Null>	36" to >48"	More than 2%
2023074	No	B	Poor	<Null>	48" to >60"	More than 2%
2023075	No	B	Poor	<Null>	48" to >60"	More than 2%
2023076	No	B	Poor	<Null>	48" to >60"	More than 2%
2023077	No	B	Poor	Sidewalk Driveway Interface	48" to >60"	More than 2%
2023078	No	B	Poor	Sidewalk Driveway Interface	<Null>	<Null>
2023079	No	B	Poor	Sidewalk Driveway Interface	<Null>	<Null>
2023080	No	B	Poor	Sidewalk Driveway Interface	<Null>	<Null>
2023081	No	B	Poor	Sidewalk Driveway Interface	<Null>	<Null>

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Grade	Condition	SDI	Width	Cross_Slope
2023082	No	B	Poor	Sidewalk Driveway Interface	<Null>	<Null>
2023083	No	B	Poor	Sidewalk Driveway Interface	<Null>	<Null>
2023084	No	C	Very Poor	<Null>	48" to >60"	More than 2%
2023085	No	C	Very Poor	<Null>	48" to >60"	Up to or equal to 2%
2023086	No	C	Very Poor	<Null>	48" to >60"	<Null>
2023087	No	A	Fair or Better	<Null>	48" to >60"	Up to or equal to 2%
2023088	No	C	Very Poor	Sidewalk Driveway Interface	<Null>	<Null>
2023089	No	B	Poor	Sidewalk Driveway Interface	36" to >48"	<Null>
2023090	No	B	Poor	<Null>	48" to >60"	<Null>
2023091	No	B	Poor	Sidewalk Driveway Interface	48" to >60"	<Null>
2023092	No	B	Poor	Sidewalk Driveway Interface	<Null>	<Null>
2023093	No	B	Poor	<Null>	48" to >60"	<Null>
2023094	No	B	Poor	<Null>	60" or more	<Null>
2023095	No	C	Very Poor	Sidewalk Driveway Interface	<Null>	<Null>
2023096	No	B	Poor	<Null>	48" to >60"	<Null>
2023097	No	A	Fair or Better	Sidewalk Driveway Interface	48" to >60"	Up to or equal to 2%
2023098	No	B	Poor	<Null>	36" to >48"	More than 2%
2023099	No	B	Poor	<Null>	36" to >48"	Up to or equal to 2%
2023100	No	B	Poor	<Null>	36" to >48"	Up to or equal to 2%

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Grade	Condition	SDI	Width	Cross_Slope
2023101	No	B	Poor	<Null>	36" to >48"	Up to or equal to 2%
2023102	No	B	Poor	<Null>	36" to >48"	Up to or equal to 2%
2023103	No	B	Poor	<Null>	36" to >48"	More than 2%
2023104	No	B	Fair or Better	<Null>	48" to >60"	Up to or equal to 2%
2023105	No	B	Poor	<Null>	<Null>	Up to or equal to 2%
2023106	No	B	Poor	<Null>	36" to >48"	Up to or equal to 2%
2023107	No	B	Poor	Sidewalk Driveway Interface	60" or more	Up to or equal to 2%
2023108	No	B	Poor	<Null>	36" to >48"	Up to or equal to 2%
2023109	No	B	Poor	<Null>	60" or more	Up to or equal to 2%
2023110	No	B	Poor	<Null>	60" or more	Up to or equal to 2%
2023111	No	B	Poor	<Null>	36" to >48"	Up to or equal to 2%
2023112	No	B	Poor	Sidewalk Driveway Interface	60" or more	More than 2%
2023113	No	B	Poor	<Null>	60" or more	More than 2%
2023114	No	B	Poor	<Null>	60" or more	Up to or equal to 2%
2023115	No	B	Poor	<Null>	60" or more	More than 2%
2023116	No	B	Poor	<Null>	60" or more	Up to or equal to 2%
2023117	No	B	Poor	<Null>	<Null>	<Null>
2023118	No	B	Poor	<Null>	60" or more	Up to or equal to 2%
2023119	No	B	Poor	<Null>	60" or more	Up to or equal to 2%

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Grade	Condition	SDI	Width	Cross_Slope
2023120	No	B	Poor	<Null>	60" or more	Up to or equal to 2%
2023121	No	B	Poor	<Null>	60" or more	Up to or equal to 2%
2023122	No	A	Fair or Better	<Null>	60" or more	Up to or equal to 2%
2023123	No	B	Poor	<Null>	60" or more	Up to or equal to 2%
2023124	No	B	Poor	<Null>	60" or more	Up to or equal to 2%
2023125	No	B	Poor	<Null>	60" or more	More than 2%
2023126	No	C	Very Poor	<Null>	60" or more	More than 2%
2023127	No	C	Very Poor	<Null>	60" or more	<Null>
2023128	No	B	Poor	<Null>	60" or more	More than 2%
2023129	No	B	Poor	Sidewalk Driveway Interface	60" or more	More than 2%
2023130	No	C	Very Poor	<Null>	Less than 36"	<Null>
2023131	No	C	Very Poor	<Null>	60" or more	More than 2%
2023132	No	A	Fair or Better	<Null>	60" or more	<Null>
2023133	No	B	Poor	<Null>	48" to >60"	More than 2%
2023134	Yes	A	Fair or Better	<Null>	48" to >60"	Up to or equal to 2%
2023135	Yes	A	Fair or Better	<Null>	48" to >60"	Up to or equal to 2%
2023136		Other	Other	<Null>	<Null>	<Null>
2023137		Other	Other	<Null>	<Null>	<Null>
2023138		Other	Other	<Null>	36" to >48"	<Null>
2023139		Other	Other	<Null>	60" or more	More than 2%

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Grade	Condition	SDI	Width	Cross_Slope
2023140		Other	Other	<Null>	<Null>	<Null>
2023200		Other	Other	<Null>	<Null>	<Null>
2023142		Other	Other	<Null>	60" or more	Up to or equal to 2%
2023143		Other	Other	<Null>	60" or more	<Null>
2023144	No	C	Very Poor	<Null>	36" to >48"	Up to or equal to 2%

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Running_Sl	Obstacle	Notes
2023001	No	Matches roadway grade	Other	Start of PAR. Cross slope 3%. Gravel debris and deteriorating curb.
2023002	No	Matches roadway grade	<Null>	Severe pavement deterioration. Gravel debris. Vertical discontinuity along 40 feet.
2023003	No	Matches roadway grade	Other	DWI, severe pavement deterioration and Gravel debris.
2023004	No	<Null>	<Null>	End of PAR. Cracking panel and curb deterioration. Deficient curb ramp.
2023005	No	<Null>	<Null>	Start of PAR. Cross slope 3%. Missing curb ramp. Cracks in PAR. Stop sign is not within 60 inch PAR.
2023006	Yes	<Null>	<Null>	Gravel debris present, but otherwise built compliant
2023007	Yes	<Null>	<Null>	End of PAR. Compliant section of 60 inch PAR. No passing zones required this segment.
2023010	No	Matches roadway grade	<Null>	End of PAR. Deficient ramp. Crumbling curb. Overgrown vegetation on both edges of PAR.
2023011	No	Matches roadway grade	Other	Crumbling curb section
2023012	No	<Null>	<Null>	Sunken and cracked panel segments exceeding quarter inch vertical discontinuity
2023013	No	<Null>	<Null>	DWI has flare slope exceeding 10% and cracks and deterioration
2023014	No	<Null>	<Null>	Severe pavement deterioration
2023015	No	<Null>	<Null>	DWI has flare slope exceeding 10% and cracks and deterioration
2023016	No	<Null>	<Null>	DWI has flare slope exceeding 10% and cracks
2023017	No	Matches roadway grade	<Null>	Gravel debris and erosion at panel transition
2023018	No	<Null>	<Null>	DWI has flare steeper than 10% and cracks
2023019	No	Matches roadway grade	<Null>	Vertical discontinuities. Cross slope 4%.
2023020	No	<Null>	Upheaval	Vertical discontinuity quarter inch.
2023021	No	<Null>	<Null>	Vegetation, debris, blocking PAR
2023022	No	<Null>	<Null>	DWI cross slope 6%. Severe cracking.
2023023	No	<Null>	<Null>	Start of PAR. Deficient ramp.

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Running_Sl	Obstacle	Notes
2023024	No	<Null>	<Null>	End of PAR. Cross slope 3%. Deficient ramp.
2023025	No	Matches roadway grade	<Null>	Gravel and dirt debris blocking PAR
2023026	No	Matches roadway grade	<Null>	Gravel debri at panel transition
2023027	No	Matches roadway grade	<Null>	Start of PAR segment. Deficient ramp. Cracks in PAR.
2023028	No	<Null>	<Null>	End of PAR. Cracks forming in segment. Deficient ramp.
2023029	No	<Null>	<Null>	Gravel debri at panel transition
2023030	No	Matches roadway grade	<Null>	Start of PAR. Cross slopes within 3%. No passing zone this segment.
2023031	No	Matches roadway grade	<Null>	End of PAR. Deficient ramp.
2023032	No	Matches roadway grade	Vegetation	Overgrown, vegetation, blocking PAR
2023033	No	<Null>	<Null>	End of PAR. Deficient ramp.
2023034	No	Matches roadway grade	<Null>	Cross slope 6%
2023035	No	<Null>	<Null>	Start of PAR. Deficient ramp. Cross slopes of 3% along segment.
2023036	No	<Null>	<Null>	End of PAR. Deficient ramp.
2023037	No	<Null>	<Null>	Gravel and dirt debris, blocking PAR. Cross slope 3%
2023038	No	Matches roadway grade	<Null>	Gravel, debri and panel joint deterioration
2023039	No	<Null>	<Null>	Gravel and dirt debris, blocking PAR. Cross slope 5.3%.
2023040	No	Matches roadway grade	<Null>	Gravel, debri and panel joint deterioration
2023041	No	Matches roadway grade	<Null>	Cross slope 2.6%. Crumbling PAR next to utility pole
2023042	No	<Null>	<Null>	Cross slope 3%. Cracks with Gravel.
2023043	No	Matches roadway grade	Vegetation	Start of PAR. Gravel Debris and overgrown weeds along curb and PAR
2023044	No	<Null>	<Null>	Starts of PAR. No PAR barricade at corner. PAR width slightly less 48 inches. Deficient ramp. 16% cross slope, and curb lip.
2023045	No	<Null>	<Null>	DWI cross slope 20%.
2023046	No	<Null>	<Null>	4% cross slope until cemetery

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Running_Sl	Obstacle	Notes
2023047	No	<Null>	<Null>	DWI flare slopes deeper than 10% and cross slope of 16%
2023048	No	<Null>	<Null>	DWI flare slopes steeper than 10% and cross slope 4%
2023049	No	Matches roadway grade	<Null>	PAR under 48 inches. Sidewalk cracks. Cross slope 3%.
2023050	No	Matches roadway grade	<Null>	Cemetery parking segment 48 inches wide with cross slopes near 3%. Cracking.
2023051	No	Matches roadway grade	<Null>	Surface deterioration. Sidewalk slightly less than 48 inches with 3% cross slope
2023052	No	<Null>	<Null>	DWI has flare slopes exceeding 10%.
2023053	No	<Null>	<Null>	DWI has flare slopes exceeding 10%
2023054	No	<Null>	<Null>	Surface deterioration with cracks forming
2023055	No	<Null>	<Null>	Panel deterioration, upheaval, and broken pieces
2023056	No	<Null>	<Null>	DWI has flare slopes exceeding 10% and cross slope of 15%
2023057	No	<Null>	<Null>	End of PAR. Overgrown vegetation on a 48 inch wide PAR.
2023058	No	<Null>	<Null>	Start a PAR. Deficient curb ramp. Overgrown vegetation on PAR. 44 inches instead of 48.
2023059	No	<Null>	<Null>	DWI has flare slopes exceeding 10% and cross slope of 13%
2023060	No	<Null>	<Null>	DWI has flare slopes exceeding 10% and cross slope of 15%
2023061	No	<Null>	<Null>	DWI has flare slopes exceeding 10% and cross slope of 13%
2023062	No	Matches roadway grade	<Null>	End of PAR. 48 inches or a little less due to vegetation from here north.

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Running_Sl	Obstacle	Notes
2023063	No	<Null>	<Null>	Start of PAR. 48 inch PAR or a couple inches less to do to vegetations from here south. Cross slope3%.
2023064	No	<Null>	<Null>	End of PAR. 48 inch PAR or a couple inches less to do to vegetations from here north. Cross slope3%.
2023065	No	<Null>	<Null>	Start of PAR. Surface deterioration
2023066	No	<Null>	<Null>	End of PAR. Surface deterioration
2023067	No	Matches roadway grade	<Null>	Start of PAR. 48 inches this entire segment. Cross slopes between 2 to 3%.
2023068	No	Matches roadway grade	<Null>	End of PAR. Some cracking of panels north of here.
2023069	No	Matches roadway grade	<Null>	Start of PAR. Width 46 inches. Overgrown vegetation may make it 48 inches.
2023070	No	Matches roadway grade	<Null>	DWI has flares exceeding 10%. Cross slope 12%.
2023071	No	Matches roadway grade	<Null>	Cross slopes within 2 to 3% This segment 42 inches to next intersection South
2023072	No	Matches roadway grade	<Null>	End of PAR. Cross low 5%. Sidewalk wits 48 inches. North of here might have vegetation encroaching to make it less than 48 inches.
2023073	No	<Null>	<Null>	Start of PAR. 42 inch wide. Could be 48 if overgrown vegetation is removed. Cross slope 2.5%. Cracks in the first few panels south of here.
2023074	No	Matches roadway grade	<Null>	Sidewalk south of here is 48 inches. DWI has flare slopes exceeding 10%.
2023075	No	<Null>	<Null>	DWI has flare slopes exceeding 10%
2023076	No	Matches roadway grade	<Null>	DWI has flare slopes exceeding 10%
2023077	No	Matches roadway grade	<Null>	DWI has flare slopes exceeding 10%
2023078	No	<Null>	<Null>	DWI steep slopes
2023079	No	<Null>	<Null>	DWI
2023080	No	<Null>	<Null>	DWI
2023081	No	<Null>	<Null>	DWI

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Running_Sl	Obstacle	Notes
2023082	No	<Null>	<Null>	DWI
2023083	No	<Null>	<Null>	DWI
2023084	No	Matches roadway grade	<Null>	End of PAR. 48 inches wide from here north. Occasional cracking. 48 inch width here.
2023085	No	<Null>	<Null>	Gravel and wide gaps between panels
2023086	No	<Null>	<Null>	Cracks and broken panels
2023087	No	<Null>	<Null>	Overgrown vegetation on 48 inch PAR
2023088	No	<Null>	<Null>	Undefined PAR across the driveway
2023089	No	<Null>	<Null>	Surface deterioration
2023090	No	<Null>	Vegetation	Overgrown vegetation and some gravel debris
2023091	No	<Null>	<Null>	Gravel debris, some cracking
2023092	No	<Null>	<Null>	DWI to West PAR vertical discontinuity more than 1/4 inch
2023093	No	<Null>	<Null>	<Null>
2023094	No	<Null>	<Null>	<Null>
2023095	No	<Null>	<Null>	DWI
2023096	No	Matches roadway grade	<Null>	PAR with 48 inches +42 to curb and 30 inches to fence
2023097	No	<Null>	<Null>	DWI flush with PAR
2023098	No	Matches roadway grade	<Null>	Cross slopes 3%. PAR 44 inches wide +42 inch wide extra space to curb.
2023099	No	Matches roadway grade	<Null>	46 inch wide PAR +40 inches extra to curb
2023100	No	Matches roadway grade	<Null>	46 inch wide PAR +40 inches extra to curb

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Running_Sl	Obstacle	Notes
2023101	No	<Null>	<Null>	Sidewalk itself in good condition.42 inch wide PAR in front of school bus parking
2023102	No	<Null>	<Null>	Vertical discontinuity in utility access, sidewalk panel
2023103	No	Matches roadway grade	<Null>	End of PAR. Cross slope 7%.
2023104	No	Matches roadway grade	<Null>	Start of PAR. PAR 48 inches +42 extra inches to curb.
2023105	No	<Null>	<Null>	PAR could be 48 inches if debris and vegetation is removed
2023106	No	<Null>	<Null>	Monitor vertical discontinuities of panels
2023107	No	<Null>	<Null>	DWI flush with PAR 2.7% Cross slope
2023108	No	Matches roadway grade	Vegetation	PAR width 46 inches but likely due to overgrown grass. 44 extra inches to curb.
2023109	No	Matches roadway grade	Vegetation	<Null>
2023110	No	Matches roadway grade	Vegetation	<Null>
2023111	No	Matches roadway grade	Vegetation	End of PAR. 46 inch PAR but likely 48 if grass is trimmed plus 44 inches extra to curb Sign is outside 48 inch PAR route
2023112	No	Matches roadway grade	<Null>	DWI flares exceed 10% and 6% Krasa
2023113	No	<Null>	<Null>	End of PAR. 3% cross slope
2023114	No	Matches roadway grade	<Null>	Remove overgrown vegetation. Cracks.
2023115	No	Matches roadway grade	<Null>	Cross slope 3%. Remove overgrown vegetation.
2023116	No	Matches roadway grade	Vegetation	72 inches wide with 30 inch extra to curb. Remove debris and vegetation.
2023117	No	<Null>	Vegetation	DWI flushed with PAR. Remove debris. Cracks.
2023118	No	<Null>	<Null>	72 inches wide with 30 inch extra to curb. Crack in panel. Remove debris and vegetation.
2023119	No	<Null>	<Null>	60 inch wide PAR +48 inches to curb. Cracks in panels. Remove vegetation and debris.

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Running_Sl	Obstacle	Notes
2023120	No	<Null>	Vegetation	60 inch wide PAR +48 inches to curb. Remove vegetation and debris. Cracks.
2023121	No	Matches roadway grade	Vegetation	64 inch wide PAR +48 inches to curb. Remove vegetation and debris.
2023122	No	Matches roadway grade	<Null>	DWI flush with PAR. Cracks.
2023123	No	Matches roadway grade	Vegetation	64 inch wide PAR +48 inches to curb. Remove vegetation and debris.
2023124	No	Matches roadway grade	<Null>	End of PAR and curb ramp photo. No DWS.
2023125	No	Matches roadway grade	<Null>	Start of PAR and curb ramp photo. Curb ramp running slope. OK. Curb ramp cross slope 4%. No DWS.
2023126	No	<Null>	<Null>	End of PAR and curb ramp photo. Ramp running sup 13%. Ramp cross slope 3%. No DWS.
2023127	No	<Null>	<Null>	Vegetation and debris makes 72 inches impassable
2023128	No	<Null>	<Null>	72 inches of PAR continues past
2023129	No	<Null>	<Null>	3% cross look for PAR flushed with driveway interface
2023130	No	Matches roadway grade	<Null>	Overgrown vegetation makes PAR impassable
2023131	No	Matches roadway grade	<Null>	Cross slope, 3%
2023132	No	Matches roadway grade	Vegetation	Best looking section could be 78 inches with cleared vegetation. Vertical discontinuity with adjacent segments
2023133	No	Matches roadway grade	Vegetation	Could be 60 inches but functionally 48 inches with 20 inch extra to curb
2023134	Yes	Matches roadway grade	<Null>	<Null>
2023135	Yes	Matches roadway grade	<Null>	<Null>
2023136		<Null>	<Null>	No PAR between ADA stall and field seating
2023137		<Null>	<Null>	No PAR between ADA stall and field seating
2023138		<Null>	<Null>	1 inch plus vertical discontinuity
2023139		Matches roadway grade	<Null>	4%

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Running_Sl	Obstacle	Notes
2023140		<Null>	<Null>	No sidewalks at Canyon Creek Middle School
2023200		<Null>	<Null>	No sidewalks at mill a school
2023142		Matches roadway grade	Upheaval	6 foot PAR with 20 inches extra to back of curb. Multiple vertical discontinuities with the cones. Poor blended transition to shoulder no DWS.
2023143		Matches roadway grade	<Null>	Use for curb ramps as well. Running soap, 9%. Cross slope within 2%. No DWS.
2023144	No	Matches roadway grade	<Null>	Washougal Bridge

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Passing Zone Dimensions	SW Width Change Point	SW_Photo_ID
2023001	No	No passing zone this segment	<Null>	SW_2023001.jpg
2023002	No	<Null>	<Null>	SW_2023002.jpg
2023003	No	<Null>	<Null>	SW_2023003.jpg
2023004	No	<Null>	<Null>	SW_2023004.jpg
2023005	No	No passing zone this segment	<Null>	SW_2023005.jpg
2023006	Yes	<Null>	<Null>	SW_2023006.jpg
2023007	Yes	<Null>	<Null>	SW_2023007.jpg
2023010	No	No passing zone this segment	<Null>	SW_2023010.jpg
2023011	No	<Null>	<Null>	SW_2023011.jpg
2023012	No	<Null>	<Null>	SW_2023012.jpg
2023013	No	<Null>	<Null>	SW_2023013.jpg
2023014	No	<Null>	<Null>	SW_2023014.jpg
2023015	No	<Null>	<Null>	SW_2023015.jpg
2023016	No	<Null>	<Null>	SW_2023016.jpg
2023017	No	<Null>	<Null>	SW_2023017.jpg
2023018	No	<Null>	<Null>	SW_2023018.jpg
2023019	No	<Null>	<Null>	SW_2023019.jpg
2023020	No	<Null>	<Null>	SW_2023020.jpg
2023021	No	<Null>	<Null>	SW_2023021.jpg
2023022	No	<Null>	<Null>	SW_2023022.jpg
2023023	No	No passing zone this segment	<Null>	SW_2023023.jpg

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Passing Zone Dimensions	SW Width Change Point	SW_Photo_ID
2023024	No	<Null>	<Null>	SW_2023024.jpg
2023025	No	<Null>	<Null>	SW_2023025.jpg
2023026	No	<Null>	<Null>	SW_2023026.jpg
2023027	No	No passing zone this segment	<Null>	SW_2023027.jpg
2023028	No	<Null>	<Null>	SW_2023028.jpg
2023029	No	<Null>	<Null>	SW_2023029.jpg
2023030	No	<Null>	<Null>	SW_2023030.jpg
2023031	No	<Null>	<Null>	SW_2023031.jpg
2023032	No	Segment under 200 feet - no passing zone required	<Null>	SW_2023032.jpg
2023033	No	<Null>	<Null>	SW_2023033.jpg
2023034	No	<Null>	<Null>	SW_2023034.jpg
2023035	No	No, passing zones this segment	<Null>	SW_2023035.jpg
2023036	No	<Null>	<Null>	SW_2023036.jpg
2023037	No	<Null>	<Null>	SW_2023037.jpg
2023038	No	<Null>	<Null>	SW_2023038.jpg
2023039	No	<Null>	<Null>	SW_2023039.jpg
2023040	No	<Null>	<Null>	SW_2023040.jpg
2023041	No	<Null>	<Null>	SW_2023041.jpg
2023042	No	<Null>	<Null>	SW_2023042.jpg
2023043	No	No passing zone this segment	No width change	SW_2023043.jpg
2023044	No	No passing zone from here to cemetery	<Null>	SW_2023044.jpg
2023045	No	<Null>	<Null>	SW_2023045.jpg
2023046	No	<Null>	<Null>	SW_2023046.jpg

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Passing Zone Dimensions	SW Width Change Point	SW_Photo_ID
2023047	No	<Null>	<Null>	SW_2023047.jpg
2023048	No	<Null>	<Null>	SW_2023048.jpg
2023049	No	<Null>	<Null>	SW_2023049.jpg
2023050	No	<Null>	Yes. 48 inch south oh this point	SW_2023050.jpg
2023051	No	<Null>	Plus -3 inches less than 48 inches from here South	SW_2023051.jpg
2023052	No	<Null>	<Null>	SW_2023052.jpg
2023053	No	<Null>	<Null>	SW_2023053.jpg
2023054	No	<Null>	48 inches wide here South	SW_2023054.jpg
2023055	No	No, passing zones	<Null>	SW_2023055.jpg
2023056	No	<Null>	<Null>	SW_2023056.jpg
2023057	No	<Null>	<Null>	SW_2023057.jpg
2023058	No	No, passing zones this segment	This sidewalk could be 48 inches. Overgrown vegetation makes it less than.	SW_2023058.jpg
2023059	No	<Null>	<Null>	SW_2023059.jpg
2023060	No	<Null>	<Null>	SW_2023060.jpg
2023061	No	<Null>	<Null>	SW_2023061.jpg
2023062	No	No passing zone this segment to cemetery	<Null>	SW_2023062.jpg

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Passing Zone Dimensions	SW Width Change Point	SW_Photo_ID
2023063	No	No passing zone this segment	<Null>	SW_2023063.jpg
2023064	No	<Null>	<Null>	SW_2023064.jpg
2023065	No	No passing zone this segment	48 inches from here South	SW_2023065.jpg
2023066	No	<Null>	<Null>	SW_2023066.jpg
2023067	No	No passing zone this segment	<Null>	SW_2023067.jpg
2023068	No	No passing zone this segment	<Null>	SW_2023068.jpg
2023069	No	No passing zone this segment	Changes to slightly less than 48.	SW_2023069.jpg
2023070	No	<Null>	<Null>	SW_2023070.jpg
2023071	No	No passing zone this segment	Changes to 42 inches wide here south	SW_2023071.jpg
2023072	No	No passing zone this segment	<Null>	SW_2023072.jpg
2023073	No	No passing zone this segment	<Null>	SW_2023073.jpg
2023074	No	<Null>	<Null>	SW_2023074.jpg
2023075	No	<Null>	<Null>	SW_2023075.jpg
2023076	No	<Null>	<Null>	SW_2023076.jpg
2023077	No	<Null>	<Null>	SW_2023077.jpg
2023078	No	<Null>	<Null>	SW_2023078.jpg
2023079	No	<Null>	<Null>	SW_2023079.jpg
2023080	No	<Null>	<Null>	SW_2023080.jpg
2023081	No	<Null>	<Null>	SW_2023081.jpg

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Passing Zone Dimensions	SW Width Change Point	SW_Photo_ID
2023082	No	<Null>	<Null>	SW_2023082.jpg
2023083	No	<Null>	<Null>	SW_2023083.jpg
2023084	No	No passing zone north of here	<Null>	SW_2023084.jpg
2023085	No	<Null>	<Null>	SW_2023085.jpg
2023086	No	<Null>	<Null>	SW_2023086.jpg
2023087	No	<Null>	<Null>	SW_2023087.jpg
2023088	No	<Null>	<Null>	SW_2023088.jpg
2023089	No	<Null>	PAR 40 inches wide, but has overgrown vegetation from here	SW_2023089.jpg
2023090	No	<Null>	<Null>	SW_2023090.jpg
2023091	No	<Null>	<Null>	SW_2023091.jpg
2023092	No	<Null>	<Null>	SW_2023092.jpg
2023093	No	<Null>	Changes to 48 inches wide here with 40 inches to curb and 24 inches to Wall	SW_2023093.jpg
2023094	No	<Null>	PAR 60 inches wide with 40 inches to curb and 12 inches to Wall	SW_2023094.jpg
2023095	No	<Null>	<Null>	SW_2023095.jpg
2023096	No	<Null>	<Null>	SW_2023096.jpg
2023097	No	<Null>	<Null>	SW_2023097.jpg
2023098	No	<Null>	<Null>	SW_2023098.jpg
2023099	No	No passing zone this segment	<Null>	SW_2023099.jpg
2023100	No	No passing zone this segment	<Null>	SW_2023100.jpg

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Passing Zone Dimensions	SW Width Change Point	SW_Photo_ID
2023101	No	No passing zone this segment	Changes to 42 inches wide here	SW_2023101.jpg
2023102	No	<Null>	<Null>	SW_2023102.jpg
2023103	No	<Null>	<Null>	SW_2023103.jpg
2023104	No	No passing zone this segment	Change to 48 inch PAR east of here	SW_2023104.jpg
2023105	No	<Null>	<Null>	SW_2023105.jpg
2023106	No	<Null>	<Null>	SW_2023106.jpg
2023107	No	<Null>	<Null>	SW_2023107.jpg
2023108	No	<Null>	<Null>	SW_2023108.jpg
2023109	No	7' x 11' passing zone surface deterioration	<Null>	SW_2023109.jpg
2023110	No	7' x 11' passing zone surface deterioration	<Null>	SW_2023110.jpg
2023111	No	<Null>	<Null>	SW_2023111.jpg
2023112	No	<Null>	<Null>	SW_2023112.jpg
2023113	No	<Null>	<Null>	SW_2023113.jpg
2023114	No	<Null>	<Null>	SW_2023114.jpg
2023115	No	No passing zone this segment	<Null>	SW_2023115.jpg
2023116	No	<Null>	<Null>	SW_2023116.jpg
2023117	No	<Null>	<Null>	SW_2023117.jpg
2023118	No	<Null>	<Null>	SW_2023118.jpg
2023119	No	<Null>	64 inch wide PAR from here East	SW_2023119.jpg

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Passing Zone Dimensions	SW Width Change Point	SW_Photo_ID
2023120	No	<Null>	<Null>	SW_2023120.jpg
2023121	No	<Null>	<Null>	SW_2023121.jpg
2023122	No	<Null>	<Null>	SW_2023122.jpg
2023123	No	<Null>	<Null>	SW_2023123.jpg
2023124	No	<Null>	<Null>	SW_2023124.jpg
2023125	No	No, passing zone this segment	Still still 5 foot PAR with 18 extra inches to curb	SW_2023125.jpg
2023126	No	<Null>	<Null>	SW_2023126.jpg
2023127	No	<Null>	<Null>	SW_2023127.jpg
2023128	No	<Null>	<Null>	SW_2023128.jpg
2023129	No	<Null>	<Null>	SW_2023129.jpg
2023130	No	<Null>	<Null>	SW_2023130.jpg
2023131	No	<Null>	Change to 5 feet PAR with 20 inch extra to curb and overgrown vegetation	SW_2023131.jpg
2023132	No	<Null>	6.5 feet newer panels.	SW_2023132.jpg
2023133	No	No passing zone this segment	<Null>	SW_2023133.jpg
2023134	Yes	<Null>	<Null>	SW_2023134.jpg
2023135	Yes	<Null>	<Null>	SW_2023135.jpg
2023136		<Null>	<Null>	SW_2023136.jpg
2023137		<Null>	<Null>	SW_2023137.jpg
2023138		<Null>	<Null>	SW_2023138.jpg
2023139		<Null>	<Null>	SW_2023139.jpg

2023 Skamania County
GIS Sidewalk Spot ADA Data

TSI Sidewalk ID	SW_ADA_Compliance	Passing Zone Dimensions	SW Width Change Point	SW_Photo_ID
2023140		<Null>	<Null>	SW_2023140A.jpg, SW_2023140B.jpg
2023200		<Null>	<Null>	SW_2023141A.jpg, SW_2023141B.jpg, SW_2023141C.jpg,
2023142		No passing zone this segment	<Null>	SW_2023142.jpg
2023143		<Null>	<Null>	SW_2023143.jpg
2023144	No	<Null>	<Null>	SW_2023144.jpg