

**Americans with Disabilities Act (ADA)  
ADA Transition Plan for the Public Right-of-Way**



## **Appendix B1**

**GIS Curb Ramp ADA Inventory and Prioritization**

**May 2024**

**Prepared by Transportation Solutions, Inc.**



### Curb Ramp Inventory Data Fields and Attributes Collected in 2023

No	Field	Attribute
1	Grade	A (Fair/Better)
		B (Poor)
		C (Very Poor)
		D (Missing)
2	Condition	Fair or Better
		Poor
		Very Poor
		Missing (Needed but does not Exist)
3	Ramp Width (unobstructed and excluding flares)	60" or greater
		48" to > 60" (PROWAG)
		36" to > 48" (ADAAG)
		Less than 36"
4	DWS (Detectable Warning Surface)	Compliant (Truncated Domes with contrasting color)
		Old Standard (Diamond/Exposed Aggregate)
		No DWS (Non-Compliant)
5	Ramp Type	Perpendicular (triangular wings)
		Perpendicular (flares without triangular panels)
		Parallel Single Direction – DWS Within Landing
		Parallel Single Direction – Returned Curb
		Parallel - Diagonally-Oriented to Intersection
		Combination
		Blended Transition
		Other
6	Running Slope	Up to or equal to 8.3%
		More than 8.3%
7	Cross Slope	Up to or equal to 2%
		More than 2%
8	Landing Present	Yes
		No
9	Landing Dimensions	4 x 4 feet or greater
		Less than 4 x 4 feet
10	Flare Slope (for Perpendicular Ramps)	Up to or equal to 10%
		More than 10%
11	Cross Slope = Roadway Grade (steep grades)	Yes
		No
	Landing (PAR) Running Slope	Up to or equal to 2%
		More than 2%
12	Landing (PAR) Cross Slope	Up to or equal to 2%
		More than 2%

No	Field	Attribute
13	Curb Lip	No Curb Lip
		Minor Curb Lip
		Major Curb Lip
13	Notes	As needed
14	Attachments	Photo attached as .jpg
15	ADA Compliant	Yes
		No

Skamania County  
2023 Curb Ramp GIS ADA Data

TSI Curb Ramp ID	ADA Compliant	Grade	Condition	Ramp Width
2023001	No	C	Very Poor	36" to > 48" (ADAAG)
2023002		Other	Other	<Null>
2023003		Other	Other	60" or greater
2023004	No	C	Very Poor	48" to > 60" (PROWAG)
2023005	No	D	Missing (needed but does not exist)	<Null>
2023006	No	D	Missing (needed but does not exist)	<Null>
2023007	No	C	Very Poor	48" to > 60" (PROWAG)
2023008	No	C	Very Poor	36" to > 48" (ADAAG)
2023009	No	C	Very Poor	36" to > 48" (ADAAG)
2023010	No	D	Missing (needed but does not exist)	<Null>
2023011	No	D	Missing (needed but does not exist)	<Null>
2023012	No	D	Missing (needed but does not exist)	<Null>
2023013	No	D	Missing (needed but does not exist)	60" or greater
2023014	No	C	Very Poor	60" or greater
2023015	No	B	Poor	60" or greater
2023016	No	D	Missing (needed but does not exist)	<Null>
2023017	No	B	Poor	48" to > 60" (PROWAG)
2023018	No	B	Poor	48" to > 60" (PROWAG)
2023019		Other	Other	<Null>
2023020		Other	Other	60" or greater
2023021	No	D	Missing (needed but does not exist)	<Null>

Skamania County  
2023 Curb Ramp GIS ADA Data

TSI Curb Ramp ID	ADA Compliant	Grade	Condition	Ramp Width
2023022	No	C	Very Poor	60" or greater
2023023	No	D	Missing (needed but does not exist)	<Null>
2023024	No	D	Missing (needed but does not exist)	<Null>
2023025		Other	Other	<Null>
2023026		Other	Other	36" to > 48" (ADAAG)
2023027		Other	Other	<Null>
2023028	No	C	Very Poor	36" to > 48" (ADAAG)
2023029	No	C	Very Poor	36" to > 48" (ADAAG)
2023030	No	C	Very Poor	36" to > 48" (ADAAG)
2023031	No	B	Poor	36" to > 48" (ADAAG)
2023032	No	D	Missing (needed but does not exist)	<Null>
2023033	No	A	Fair or Better	48" to > 60" (PROWAG)
2023034	No	D	Missing (needed but does not exist)	<Null>
2023035	No	C	Very Poor	Less than 36"
2023036	No	C	Very Poor	48" to > 60" (PROWAG)
2023037	No	C	Very Poor	Less than 36"
2023038	No	C	Very Poor	36" to > 48" (ADAAG)
2023039	No	C	Very Poor	48" to > 60" (PROWAG)
2023040	No	C	Very Poor	48" to > 60" (PROWAG)
2023041	No	C	Very Poor	48" to > 60" (PROWAG)
2023042	No	B	Poor	60" or greater
2023043	No	C	Very Poor	Less than 36"
2023044	No	C	Very Poor	36" to > 48" (ADAAG)
2023045	No	C	Very Poor	36" to > 48" (ADAAG)
2023046	No	C	Very Poor	36" to > 48" (ADAAG)

Skamania County  
2023 Curb Ramp GIS ADA Data

TSI Curb Ramp ID	ADA Compliant	Grade	Condition	Ramp Width
2023047	No	C	Very Poor	36" to > 48" (ADAAG)
2023048	No	C	Very Poor	36" to > 48" (ADAAG)
2023049	No	C	Very Poor	36" to > 48" (ADAAG)
2023050	No	C	Very Poor	36" to > 48" (ADAAG)
2023051	No	C	Very Poor	48" to > 60" (PROWAG)
2023052	No	C	Very Poor	36" to > 48" (ADAAG)
2023053	No	C	Very Poor	Less than 36"
2023054	No	C	Very Poor	36" to > 48" (ADAAG)
2023055	No	C	Very Poor	36" to > 48" (ADAAG)
2023056	Yes	A	Fair or Better	60" or greater
2023057	No	D	Missing (needed but does not exist)	<Null>
2023058	No	D	Missing (needed but does not exist)	<Null>
2023061		Other	Other	<Null>
2023062	No	C	Very Poor	48" to > 60" (PROWAG)
2023063	No	C	Very Poor	48" to > 60" (PROWAG)
2023064	No	C	Very Poor	48" to > 60" (PROWAG)
2023065	No	C	Very Poor	48" to > 60" (PROWAG)
2023066	No	C	Very Poor	48" to > 60" (PROWAG)
2023067	No	C	Very Poor	48" to > 60" (PROWAG)
2023068		Other	Other	<Null>
2023069		Other	Other	<Null>
2023070		Other	Other	<Null>
2023071		Other	Other	<Null>
2023072		Other	Other	<Null>
2023073	No	C	Very Poor	36" to > 48" (ADAAG)

Skamania County  
2023 Curb Ramp GIS ADA Data

TSI Curb Ramp ID	ADA Compliant	DWS
2023001	No	No DWS (Non-Compliant)
2023002		No DWS (Non-Compliant)
2023003		No DWS (Non-Compliant)
2023004	No	No DWS (Non-Compliant)
2023005	No	<Null>
2023006	No	<Null>
2023007	No	No DWS (Non-Compliant)
2023008	No	No DWS (Non-Compliant)
2023009	No	No DWS (Non-Compliant)
2023010	No	<Null>
2023011	No	<Null>
2023012	No	<Null>
2023013	No	No DWS (Non-Compliant)
2023014	No	No DWS (Non-Compliant)
2023015	No	Old Standard (Diamond/Exposed Aggregate)
2023016	No	<Null>
2023017	No	Old Standard (Diamond/Exposed Aggregate)
2023018	No	Old Standard (Diamond/Exposed Aggregate)
2023019		<Null>
2023020		No DWS (Non-Compliant)
2023021	No	<Null>

Skamania County  
2023 Curb Ramp GIS ADA Data

TSI Curb Ramp ID	ADA Compliant	DWS
2023022	No	No DWS (Non-Compliant)
2023023	No	<Null>
2023024	No	<Null>
2023025		No DWS (Non-Compliant)
2023026		<Null>
2023027		<Null>
2023028	No	No DWS (Non-Compliant)
2023029	No	No DWS (Non-Compliant)
2023030	No	No DWS (Non-Compliant)
2023031	No	Old Standard (Diamond/Exposed Aggregate)
2023032	No	<Null>
2023033	No	Compliant (Truncated Domes with contrasting color)
2023034	No	<Null>
2023035	No	No DWS (Non-Compliant)
2023036	No	No DWS (Non-Compliant)
2023037	No	No DWS (Non-Compliant)
2023038	No	No DWS (Non-Compliant)
2023039	No	No DWS (Non-Compliant)
2023040	No	No DWS (Non-Compliant)
2023041	No	No DWS (Non-Compliant)
2023042	No	Old Standard (Diamond/Exposed Aggregate)
2023043	No	No DWS (Non-Compliant)
2023044	No	No DWS (Non-Compliant)
2023045	No	No DWS (Non-Compliant)
2023046	No	No DWS (Non-Compliant)



Skamania County  
2023 Curb Ramp GIS ADA Data

TSI Curb Ramp ID	ADA Compliant	DWS
2023047	No	No DWS (Non-Compliant)
2023048	No	No DWS (Non-Compliant)
2023049	No	No DWS (Non-Compliant)
2023050	No	No DWS (Non-Compliant)
2023051	No	No DWS (Non-Compliant)
2023052	No	No DWS (Non-Compliant)
2023053	No	No DWS (Non-Compliant)
2023054	No	No DWS (Non-Compliant)
2023055	No	No DWS (Non-Compliant)
2023056	Yes	Compliant (Truncated Domes with contrasting color)
2023057	No	<Null>
2023058	No	No DWS (Non-Compliant)
2023061		No DWS (Non-Compliant)
2023062	No	No DWS (Non-Compliant)
2023063	No	No DWS (Non-Compliant)
2023064	No	No DWS (Non-Compliant)
2023065	No	No DWS (Non-Compliant)
2023066	No	No DWS (Non-Compliant)
2023067	No	No DWS (Non-Compliant)
2023068		No DWS (Non-Compliant)
2023069		No DWS (Non-Compliant)
2023070		<Null>
2023071		<Null>
2023072		<Null>
2023073	No	No DWS (Non-Compliant)

Skamania County  
2023 Curb Ramp GIS ADA Data

TSI Curb Ramp ID	ADA Compliant	Ramp Type	Running Slope	Cross Slope
2023001	No	Other	More than 8.3%	More than 2%
2023002		Other	<Null>	More than 2%
2023003		Blended Transition	Up to or equal to 8.3%	Up to or equal to 2%
2023004	No	Other	Up to or equal to 8.3%	More than 2%
2023005	No	<Null>	<Null>	<Null>
2023006	No	<Null>	<Null>	More than 2%
2023007	No	Other	Up to or equal to 8.3%	Up to or equal to 2%
2023008	No	Combination	Up to or equal to 8.3%	Up to or equal to 2%
2023009	No	<Null>	Up to or equal to 8.3%	Up to or equal to 2%
2023010	No	<Null>	<Null>	<Null>
2023011	No	<Null>	<Null>	<Null>
2023012	No	<Null>	<Null>	<Null>
2023013	No	Other	Up to or equal to 8.3%	More than 2%
2023014	No	<Null>	Up to or equal to 8.3%	Up to or equal to 2%
2023015	No	Parallel Single Direction – DWS Within Landing	More than 8.3%	More than 2%
2023016	No	<Null>	<Null>	<Null>
2023017	No	Parallel Single Direction – DWS Within Landing	Up to or equal to 8.3%	More than 2%
2023018	No	Parallel Single Direction – DWS Within Landing	Up to or equal to 8.3%	More than 2%
2023019		<Null>	<Null>	<Null>
2023020		Blended Transition	Up to or equal to 8.3%	More than 2%
2023021	No	<Null>	<Null>	<Null>

Skamania County  
2023 Curb Ramp GIS ADA Data

TSI Curb Ramp ID	ADA Compliant	Ramp Type	Running Slope	Cross Slope
2023022	No	<Null>	Up to or equal to 8.3%	More than 2%
2023023	No	<Null>	<Null>	<Null>
2023024	No	<Null>	<Null>	<Null>
2023025		<Null>	<Null>	<Null>
2023026		<Null>	More than 8.3%	Up to or equal to 2%
2023027		<Null>	<Null>	<Null>
2023028	No	<Null>	Up to or equal to 8.3%	Up to or equal to 2%
2023029	No	<Null>	More than 8.3%	Up to or equal to 2%
2023030	No	<Null>	More than 8.3%	More than 2%
2023031	No	Parallel Single Direction – DWS Within Landing	Up to or equal to 8.3%	Up to or equal to 2%
2023032	No	<Null>	<Null>	<Null>
2023033	No	<Null>	Up to or equal to 8.3%	Up to or equal to 2%
2023034	No	<Null>	<Null>	<Null>
2023035	No	<Null>	Up to or equal to 8.3%	More than 2%
2023036	No	<Null>	Up to or equal to 8.3%	More than 2%
2023037	No	<Null>	Up to or equal to 8.3%	More than 2%
2023038	No	<Null>	More than 8.3%	More than 2%
2023039	No	<Null>	Up to or equal to 8.3%	More than 2%
2023040	No	<Null>	More than 8.3%	More than 2%
2023041	No	<Null>	Up to or equal to 8.3%	More than 2%
2023042	No	<Null>	Up to or equal to 8.3%	Up to or equal to 2%
2023043	No	<Null>	More than 8.3%	<Null>
2023044	No	<Null>	More than 8.3%	More than 2%
2023045	No	<Null>	More than 8.3%	<Null>
2023046	No	<Null>	More than 8.3%	<Null>

Skamania County  
2023 Curb Ramp GIS ADA Data

TSI Curb Ramp ID	ADA Compliant	Ramp Type	Running Slope	Cross Slope
2023047	No	<Null>	More than 8.3%	<Null>
2023048	No	<Null>	More than 8.3%	<Null>
2023049	No	<Null>	More than 8.3%	<Null>
2023050	No	<Null>	More than 8.3%	<Null>
2023051	No	Blended Transition	Up to or equal to 8.3%	Up to or equal to 2%
2023052	No	<Null>	More than 8.3%	<Null>
2023053	No	<Null>	More than 8.3%	<Null>
2023054	No	<Null>	More than 8.3%	<Null>
2023055	No	<Null>	More than 8.3%	<Null>
2023056	Yes	Perpendicular (triangular wings)	Up to or equal to 8.3%	Up to or equal to 2%
2023057	No	<Null>	<Null>	<Null>
2023058	No	<Null>	<Null>	<Null>
2023061		<Null>	<Null>	More than 2%
2023062	No	Other	Up to or equal to 8.3%	Up to or equal to 2%
2023063	No	Other	Up to or equal to 8.3%	Up to or equal to 2%
2023064	No	Other	Up to or equal to 8.3%	Up to or equal to 2%
2023065	No	Other	Up to or equal to 8.3%	More than 2%
2023066	No	Other	Up to or equal to 8.3%	Up to or equal to 2%
2023067	No	Other	Up to or equal to 8.3%	Up to or equal to 2%
2023068		Blended Transition	<Null>	<Null>
2023069		Blended Transition	<Null>	<Null>
2023070		<Null>	<Null>	<Null>
2023071		<Null>	<Null>	<Null>
2023072		<Null>	<Null>	<Null>
2023073	No	Parallel Single Direction – Returned Curb	Up to or equal to 8.3%	Up to or equal to 2%

Skamania County  
2023 Curb Ramp GIS ADA Data

TSI Curb Ramp ID	ADA Compliant	Landing Present	Landing Dimensions	Flare Slope (Perpendicular Ramps)
2023001	No	Yes	Less than 4 x 4 feet	<Null>
2023002		Yes	Less than 4 x 4 feet	<Null>
2023003		No	<Null>	<Null>
2023004	No	Yes	Less than 4 x 4 feet	<Null>
2023005	No	Yes	Less than 4 x 4 feet	<Null>
2023006	No	Yes	Less than 4 x 4 feet	<Null>
2023007	No	Yes	Less than 4 x 4 feet	<Null>
2023008	No	No	Less than 4 x 4 feet	More than 10%
2023009	No	Yes	Less than 4 x 4 feet	<Null>
2023010	No	Yes	Less than 4 x 4 feet	<Null>
2023011	No	Yes	4 x 4 feet or greater	<Null>
2023012	No	Yes	<Null>	<Null>
2023013	No	Yes	4 x 4 feet or greater	<Null>
2023014	No	Yes	4 x 4 feet or greater	<Null>
2023015	No	Yes	4 x 4 feet or greater	<Null>
2023016	No	Yes	4 x 4 feet or greater	<Null>
2023017	No	Yes	4 x 4 feet or greater	<Null>
2023018	No	Yes	4 x 4 feet or greater	<Null>
2023019		<Null>	<Null>	<Null>
2023020		Yes	4 x 4 feet or greater	<Null>
2023021	No	Yes	4 x 4 feet or greater	<Null>

Skamania County  
2023 Curb Ramp GIS ADA Data

TSI Curb Ramp ID	ADA Compliant	Landing Present	Landing Dimensions	Flare Slope (Perpendicular Ramps)
2023022	No	Yes	4 x 4 feet or greater	<Null>
2023023	No	Yes	4 x 4 feet or greater	<Null>
2023024	No	Yes	4 x 4 feet or greater	<Null>
2023025		<Null>	<Null>	<Null>
2023026		Yes	Less than 4 x 4 feet	<Null>
2023027		<Null>	<Null>	<Null>
2023028	No	Yes	Less than 4 x 4 feet	<Null>
2023029	No	Yes	Less than 4 x 4 feet	<Null>
2023030	No	No	Less than 4 x 4 feet	<Null>
2023031	No	Yes	4 x 4 feet or greater	<Null>
2023032	No	<Null>	<Null>	<Null>
2023033	No	Yes	4 x 4 feet or greater	<Null>
2023034	No	<Null>	<Null>	<Null>
2023035	No	Yes	4 x 4 feet or greater	<Null>
2023036	No	Yes	4 x 4 feet or greater	<Null>
2023037	No	Yes	Less than 4 x 4 feet	<Null>
2023038	No	Yes	4 x 4 feet or greater	<Null>
2023039	No	Yes	4 x 4 feet or greater	<Null>
2023040	No	Yes	4 x 4 feet or greater	<Null>
2023041	No	Yes	4 x 4 feet or greater	<Null>
2023042	No	Yes	4 x 4 feet or greater	<Null>
2023043	No	No	Less than 4 x 4 feet	<Null>
2023044	No	No	Less than 4 x 4 feet	<Null>
2023045	No	No	Less than 4 x 4 feet	<Null>
2023046	No	No	Less than 4 x 4 feet	<Null>

Skamania County  
2023 Curb Ramp GIS ADA Data

TSI Curb Ramp ID	ADA Compliant	Landing Present	Landing Dimensions	Flare Slope (Perpendicular Ramps)
2023047	No	No	Less than 4 x 4 feet	<Null>
2023048	No	No	Less than 4 x 4 feet	<Null>
2023049	No	No	Less than 4 x 4 feet	<Null>
2023050	No	No	Less than 4 x 4 feet	<Null>
2023051	No	Yes	4 x 4 feet or greater	<Null>
2023052	No	No	Less than 4 x 4 feet	<Null>
2023053	No	No	Less than 4 x 4 feet	<Null>
2023054	No	No	Less than 4 x 4 feet	<Null>
2023055	No	No	Less than 4 x 4 feet	<Null>
2023056	Yes	Yes	4 x 4 feet or greater	<Null>
2023057	No	<Null>	<Null>	<Null>
2023058	No	Yes	4 x 4 feet or greater	<Null>
2023061		No	Less than 4 x 4 feet	<Null>
2023062	No	Yes	4 x 4 feet or greater	<Null>
2023063	No	Yes	4 x 4 feet or greater	<Null>
2023064	No	Yes	4 x 4 feet or greater	<Null>
2023065	No	Yes	4 x 4 feet or greater	<Null>
2023066	No	Yes	4 x 4 feet or greater	<Null>
2023067	No	Yes	4 x 4 feet or greater	<Null>
2023068		<Null>	<Null>	<Null>
2023069		<Null>	<Null>	<Null>
2023070		<Null>	<Null>	<Null>
2023071		<Null>	<Null>	<Null>
2023072		<Null>	<Null>	<Null>
2023073	No	Yes	<Null>	<Null>

Skamania County  
2023 Curb Ramp GIS ADA Data

TSI Curb Ramp ID	ADA Compliant	Cross Slope Equals Roadway Grade	Landing (PAR) Running Slope	Landing (PAR) Cross Slope
2023001	No	Yes	More than 2%	More than 2%
2023002		<Null>	<Null>	More than 2%
2023003		Yes	<Null>	<Null>
2023004	No	No	Up to or equal to 2%	Up to or equal to 2%
2023005	No	<Null>	Up to or equal to 2%	More than 2%
2023006	No	<Null>	Up to or equal to 2%	More than 2%
2023007	No	<Null>	Up to or equal to 2%	More than 2%
2023008	No	<Null>	<Null>	<Null>
2023009	No	<Null>	Up to or equal to 2%	Up to or equal to 2%
2023010	No	<Null>	<Null>	<Null>
2023011	No	<Null>	<Null>	<Null>
2023012	No	<Null>	<Null>	<Null>
2023013	No	Yes	More than 2%	Up to or equal to 2%
2023014	No	<Null>	Up to or equal to 2%	Up to or equal to 2%
2023015	No	<Null>	More than 2%	Up to or equal to 2%
2023016	No	<Null>	<Null>	<Null>
2023017	No	<Null>	Up to or equal to 2%	Up to or equal to 2%
2023018	No	<Null>	Up to or equal to 2%	More than 2%
2023019		<Null>	<Null>	<Null>
2023020		<Null>	<Null>	<Null>
2023021	No	<Null>	<Null>	<Null>



Skamania County  
2023 Curb Ramp GIS ADA Data

TSI Curb Ramp ID	ADA Compliant	Cross Slope Equals Roadway Grade	Landing (PAR) Running Slope	Landing (PAR) Cross Slope
2023022	No	<Null>	Up to or equal to 2%	More than 2%
2023023	No	<Null>	<Null>	<Null>
2023024	No	<Null>	Up to or equal to 2%	Up to or equal to 2%
2023025		<Null>	<Null>	<Null>
2023026		<Null>	Up to or equal to 2%	Up to or equal to 2%
2023027		<Null>	<Null>	<Null>
2023028	No	<Null>	Up to or equal to 2%	Up to or equal to 2%
2023029	No	<Null>	More than 2%	Up to or equal to 2%
2023030	No	<Null>	<Null>	<Null>
2023031	No	<Null>	Up to or equal to 2%	Up to or equal to 2%
2023032	No	<Null>	<Null>	<Null>
2023033	No	<Null>	More than 2%	Up to or equal to 2%
2023034	No	<Null>	<Null>	<Null>
2023035	No	<Null>	More than 2%	More than 2%
2023036	No	<Null>	More than 2%	Up to or equal to 2%
2023037	No	<Null>	<Null>	<Null>
2023038	No	<Null>	More than 2%	Up to or equal to 2%
2023039	No	<Null>	Up to or equal to 2%	Up to or equal to 2%
2023040	No	<Null>	Up to or equal to 2%	Up to or equal to 2%
2023041	No	<Null>	Up to or equal to 2%	Up to or equal to 2%
2023042	No	<Null>	Up to or equal to 2%	Up to or equal to 2%
2023043	No	<Null>	<Null>	<Null>
2023044	No	<Null>	<Null>	<Null>
2023045	No	<Null>	<Null>	<Null>
2023046	No	<Null>	<Null>	<Null>

Skamania County  
2023 Curb Ramp GIS ADA Data

TSI Curb Ramp ID	ADA Compliant	Cross Slope Equals Roadway Grade	Landing (PAR) Running Slope	Landing (PAR) Cross Slope
2023047	No	<Null>	<Null>	<Null>
2023048	No	<Null>	<Null>	<Null>
2023049	No	<Null>	<Null>	<Null>
2023050	No	<Null>	<Null>	<Null>
2023051	No	<Null>	<Null>	<Null>
2023052	No	<Null>	<Null>	<Null>
2023053	No	<Null>	<Null>	<Null>
2023054	No	<Null>	<Null>	<Null>
2023055	No	<Null>	<Null>	<Null>
2023056	Yes	<Null>	Up to or equal to 2%	Up to or equal to 2%
2023057	No	<Null>	<Null>	<Null>
2023058	No	<Null>	<Null>	<Null>
2023061		<Null>	<Null>	<Null>
2023062	No	<Null>	More than 2%	<Null>
2023063	No	<Null>	<Null>	<Null>
2023064	No	<Null>	<Null>	<Null>
2023065	No	<Null>	<Null>	<Null>
2023066	No	<Null>	<Null>	<Null>
2023067	No	<Null>	<Null>	<Null>
2023068		<Null>	<Null>	<Null>
2023069		<Null>	<Null>	<Null>
2023070		<Null>	<Null>	<Null>
2023071		<Null>	<Null>	<Null>
2023072		<Null>	<Null>	<Null>
2023073	No	<Null>	<Null>	<Null>

Skamania County  
2023 Curb Ramp GIS ADA Data

TSI Curb Ramp ID	ADA Compliant	Curb Lip	Notes	TSI_CurbrRamp_Photo_ID
2023001	No	Minor Curb Lip	Cross slope 2.5%. PAR Cross slope 4%. PAR running slope 3%. Matches roadway grade. PAR width 46 inches.	2023001.jpg
2023002		<Null>	20% slope to ditch. PAR shoulder width less than 48 inches.	2023002.jpg
2023003		No Curb Lip	Connects to 2% cross slope shoulder.	2023003.jpg
2023004	No	No Curb Lip	Cross slope 3%.	2023004.jpg
2023005	No	<Null>	PAR cross slope 7%. PAR width 44 inches.	2023005.jpg
2023006	No	<Null>	PAR cross slope 4%. PAR width 44 inches.	2023006.jpg
2023007	No	Minor Curb Lip	PAR cross slope 3%. PAR width 46 inches.	2023007.jpg
2023008	No	No Curb Lip	Flare curb crumbled. No receiving ramp to south.	2023008.jpg
2023009	No	No Curb Lip	PAR width 47 inches	2023009.jpg
2023010	No	<Null>	No curb ramp at marked crosswalk	2023010.jpg
2023011	No	<Null>	No ramp at marked crosswalk	2023011.jpg
2023012	No	<Null>	No ramp at marked crosswalk. Cracks and vegetation in landing.	2023012.jpg
2023013	No	No Curb Lip	Roadway grade 6%. Could be considered missing ramp.	2023013.jpg
2023014	No	No Curb Lip	Blended transition candidate.	2023014.jpg
2023015	No	No Curb Lip	Roadway grade 12% matches PAR running slope	2023015.jpg
2023016	No	<Null>	Overgrown vegetation blocking noncompliant blended transition. Missing ramp at marked crossing.	2023016.jpg
2023017	No	No Curb Lip	Debris on PAR	2023017.jpg
2023018	No	No Curb Lip	Debris on PAR	2023018.jpg
2023019		<Null>	No ramp at end of PAR near signal. Private Property.	2023019.jpg
2023020		<Null>	Cross slop 4.6% east/west. Cross slope 0% north/south. Private Property.	2023020.jpg
2023021	No	<Null>	<Null>	2023021.jpg

Skamania County  
2023 Curb Ramp GIS ADA Data

TSI Curb Ramp ID	ADA Compliant	Curb Lip	Notes	TSI_CurbrRamp_Photo_ID
2023022	No	Minor Curb Lip	Curb crumbling with cracks next to wide PAR with curb lip and no DWS.	2023022.jpg
2023023	No	<Null>	Double curb to property frontage. Less than 36 inch PAR on west side. 60" PAR on east	2023023.jpg
2023024	No	<Null>	Grate in marked crosswalk	2023024.jpg
2023025		<Null>	PAR is shoulder and business access. Private Property.	2023025.jpg
2023026		<Null>	1 inch gap. Ramp to parking stall. Private Property.	2023026.jpg
2023027		Major Curb Lip	1+inch vertical discontinuity. Private Property.	2023027.jpg
2023028	No	No Curb Lip	PAR and ramp just shy of 48 inches	2023028.jpg
2023029	No	No Curb Lip	Ramp slope 14%. Roadway grade 4%.	2023029.jpg
2023030	No	No Curb Lip	End of PAR	2023030.jpg
2023031	No	No Curb Lip	Debris in landing. Curb deterioration.	2023031.jpg
2023032	No	<Null>	<Null>	2023032.jpg
2023033	No	No Curb Lip	Vegetation in PAR; landing cross slope exceeds maximum	2023033.jpg
2023034	No	<Null>	<Null>	2023034.jpg
2023035	No	Minor Curb Lip	<Null>	2023035.jpg
2023036	No	Minor Curb Lip	<Null>	2023036.jpg
2023037	No	Major Curb Lip	<Null>	2023037.jpg
2023038	No	No Curb Lip	PAR cross slope 4%. Overgrown vegetation.	2023038.jpg
2023039	No	No Curb Lip	<Null>	2023039.jpg
2023040	No	No Curb Lip	Ramp cross slope 10%	2023040.jpg
2023041	No	No Curb Lip	<Null>	2023041.jpg
2023042	No	Minor Curb Lip	Add DWS to end of PAR and shoulder	2023042.jpg
2023043	No	Major Curb Lip	PAR ends around the corner. Needs transition. Curb lip.	2023043.jpg
2023044	No	No Curb Lip	PAR with less than 36 inches at curb ramp	2023044.jpg
2023045	No	Major Curb Lip	<Null>	2023045.jpg
2023046	No	<Null>	<Null>	2023046.jpg

Skamania County  
2023 Curb Ramp GIS ADA Data

TSI Curb Ramp ID	ADA Compliant	Curb Lip	Notes	TSI_CurbrRamp_Photo_ID
2023047	No	Minor Curb Lip	<Null>	2023047.jpg
2023048	No	Major Curb Lip	<Null>	2023048.jpg
2023049	No	Minor Curb Lip	<Null>	2023049.jpg
2023050	No	No Curb Lip	<Null>	2023050.jpg
2023051	No	No Curb Lip	<Null>	2023051.jpg
2023052	No	No Curb Lip	<Null>	2023052.jpg
2023053	No	Major Curb Lip	<Null>	2023053.jpg
2023054	No	Minor Curb Lip	<Null>	2023054.jpg
2023055	No	Minor Curb Lip	<Null>	2023055.jpg
2023056	Yes	No Curb Lip	<Null>	2023056.jpg
2023057	No	<Null>	Marked crosswalk with no curb on either side	2023057.jpg
2023058	No	<Null>	No DWS at end of PAR	2023058.jpg
2023061		<Null>	Gravel path with mkared crossing to Cape Horn Trail.	2023061.jpg
2023062	No	Minor Curb Lip	<Null>	2023062.jpg
2023063	No	No Curb Lip	<Null>	2023063.jpg
2023064	No	No Curb Lip	<Null>	2023064.jpg
2023065	No	Minor Curb Lip	Cross slope 7%. Curb gap to pavement. Gravel debris	2023065.jpg
2023066	No	No Curb Lip	<Null>	2023066.jpg
2023067	No	No Curb Lip	Missing PAR barrier	2023067.jpg
2023068		<Null>	Observed pedestrians using to cross street to parking/gas station/convenience store/transit	2023068.jpg
2023069		<Null>	Observed pedestrians using to cross street to parking/gas station/convenience store/parking	2023069.jpg
2023070		<Null>	Marked pedestrian crossing	2023070.jpg
2023071		<Null>	Marked pedestrian crossing	2023071.jpg
2023072		<Null>	Marked pedestrian crossing	2023072.jpg
2023073	No	<Null>	Serves Washougal Bridge	2023076.jpg